

# IMSA PENALTY NOTICE TP - 24 - 30M



#### **ENTRY**

TYPE: Technical

**EVENT:** Michelin GT Challenge at VIR

**SERIES: IWSC** 

**MANUFACTURER:** Aston Martin

#### **INFRACTION**

**OFFICIALS:** IMSA Technical Committee and Supervisory Officials

IMSA Officials have reviewed the following matter and determined it to be a breach of the IMSA RULES committed by the Manufacturer and

imposes the penalty(ies) listed below.

**DATE & TIME:** 8/25/2024 3:50 PM

**LOCATION:** Technical Inspection

**REGULATION: GTD TR 2.5.1** 

**FACTS:** 

During post-Race Technical Inspection, Car #27 was found to have non-Homologated part(s) provided by the Manufacturer

#### **PENALTY**

**FINE**: \$10,000

**SIGNATURES** 

Approved by:



IMSA Technical Committee
One Daytona Boulevard | Daytona Beach, FL 32114

**IMSA Technical Committee** 

Delivered by:



IMSA Technical Committee
One Daytona Boulevard | Daytona Beach, FL 32114

**IMSA Technical Committee** 

Received by:

Aston Martin Representative



## **IMSA PENALTY NOTICE**



### **REGULATION # TR**

### 2.5. Conditions for Use of a Specific Homologation

- 2.5.1. At all times during IMSA-sanctioned Events it is the Entrant's responsibility to ensure the configuration of the Car Model represents the Homologation components of the Specification; including:
  - a. As-Homologated Configuration
  - b. As-Delivered Configuration
  - c. Parts Manual
  - d. Homologation Extension Form Configuration