

## IMSA PENALTY NOTICE TP - 24 - 40



### **ENTRY**

**32** 

TYPE: Technical

**EVENT:** Motul Petit LeMans

**SERIES: IWSC** 

**TEAM:** Korthoff/Preston Motorsports

**ENTRANT** Walter Preston

**REPRESENTATIVE:** 

**DRIVER:** 

**AFFECTED PARTY: N/A** 

### **INFRACTION**

**OFFICIAL:** Eric Haverson

The Official listed above has reviewed the following matter and determined it to be a breach of the IMSA RULES committed by the Team and

imposes the penalty(ies) listed below.

DATE & TIME: 10/13/2024 12:30:00 AM LOCATION: Technical Inspection

**REGULATION: 22.7 Technical Non-Compliance** 

FACTS: During post-Race technical inspection, GTD Car #32 was found to have camber/pressures beyond the

permitted limits per the matrix published in MMTB\_IWSC\_2024\_12\_GTDPro\_GTD

### **PENALTY**

FINE:

N/A

CHANGE: Car is moved to the back of the Class

RETURN TROPHY

SIGNATURES SIGNATURES			
Approved by:	Delivered by:	Received by:	
Matthew Kurdock	Fric Haverson	Walter Preston	

Matthew Kurdock Eric Haverson Walter Preston

KorthoffPreston Motorsports

10/13/2024 1:01:05 AM

10/13/2024 1:04:00 AM



# IMSA PENALTY NOTICE TP - 24 - 40



## **REGULATION # SR & SSR**

22.7.1. Cars out of compliance with the Technical specifications and/or regulations may be penalized by being moved to the back of class, or up to and including Removal from the results, and/or any penalty available per Art. 57.

ATT 3.6.6.C Compliance with Tire Manufacturer operational requirements is mandatory