

IMSA PENALTY NOTICE

TP - 25 - 17



ENTRY

21MAS

TYPE: Technical

EVENT: Sahlen's Six Hours of the Glen

SERIES: PCCNA

TEAM: MGM

ENTRANT Marvin Gilbert

REPRESENTATIVE:

DRIVER:

AFFECTED PARTY: N/A

INFRACTION

OFFICIAL: Todd Godek

The Official listed above has reviewed the following matter and determined it to be a breach of the IMSA RULES committed by the Team and

imposes the penalty(ies) listed below.

DATE & TIME: 6/20/2025 4:27:00 PM LOCATION: Technical Inspection

REGULATION: 22.7 Technical Non-Compliance

FACTS: During Technical Inspection following WGI Race #1, Masters Car #21 was found to have exceeded the

maximum permitted camber per 2025 Yokohama Bulletin (January 1, 2025)

PENALTY

FINE: N/A

CHANGE: Car is moved to the back of the Grid. Race #1 lap times are invalidated

RETURN TROPHY

- 11		IΑI		
\mathbf{u}	\mathbf{v}		\mathbf{v}	

Approved by:

Delivered by:

Received by:

Matthew Kurdock Scott Ellison Marvin Gilbert

Managing Director, Engineering

Manager, Technical Compliance and Scrutineering

MGM

6/20/2025 4:39:57 PM



IMSA PENALTY NOTICE TP - 25 - 17



REGULATION # SR & SSF

22.7.1. (SSR) Cars out of compliance with the Technical specifications and/or regulations may be penalized by being moved to the back of the grid, or up to and including Removal from the results and/or any penalty available per Art. 57.